



# Freeance Mobile Device Support

## Comparison Chart



8700/8703/8707

8800/8820

8830

9000

9700

8300/8310/8320

8330

8350

8520/8900

8530

Freeance Mobile Version 2.2

Y<sup>1</sup>

Y

Y<sup>4</sup>

Y<sup>3</sup>

N

Y

Y<sup>3,4</sup>

Y<sup>2</sup>

Y<sup>3</sup>

N

Freeance Mobile Version 2.4

Y<sup>1</sup>

Y

Y<sup>4</sup>

Y

Y

Y

Y<sup>4</sup>

Y<sup>2</sup>

Y

Y



Pearl

Storm

Tour

8100

8110/8120/8220

8130/8230

9500/9530

9520/9550

9630

Freeance Mobile Version 2.2

1,5

5

4,5

Y<sup>3</sup>

N

Y<sup>3</sup>

Freeance Mobile Version 2.4

1,5

5

4,5

Y

Y

Y

Notes

<sup>1</sup> With carrier-approved OS update of 4.2.1 or higher  
<sup>2</sup> With OS 4.6.1.313 or higher

<sup>3</sup> With OS versions prior to 5.0  
<sup>4</sup> Built-in GPS functionality may be disabled on certain Verizon branded devices  
<sup>5</sup> In certification testing

How can we help your business?

[www.freeance.com](http://www.freeance.com)